

MODEL

**aerosmith ST4100**

BULLETIN NO.

**ST4100-01**

DATE OF CHANGE

**Aug 2008**

DATE


**Aug 25, 2008**

Subject :

**INSTALLATION INSTRUCTION FOR SEQUENTIAL TRIP CONVERSION KIT (CN81097)**

To obtain correct action of Sequential Trigger, it is necessary to remove Spring 3130 (KK23130) and Spring 3189 (KK33189) before reassembly of Conversion kit. INSTALLATION INSTRUCTION has been revised.

<Current Installation Instruction>



<Addition>

**Remove SPRING 3130 and 3189 before reassembly Conversion kit.**

